

Kawasaki SERVICE INFORMATION

Category Recall (FDM)	
Model ZX1400A6F/ A7F/B6F/B7F	
Serial No. DAA921A/2A/3A	Date Jun. 16, 2008

Subject

Frame Breakage - RECALL -

Eligibility

Units within the frame number ranges listed are eligible for inspection and repair.

Eligible units

Model	Eligible Frame/VIN Number Range	Remark
ZX1400A6F/FL ZX1400A7F/FL/FA/FAL	JKBZXNA1√6A000023 through 010645 JKBZXNA1√7A015001 through 026292	American System
ZX1400A6F ZX1400A7F	JKBZXT40AAA000004 through 026070 ZXT40A – 000196 through 026291	European System Malaysian System
ZX1400B6F ZX1400B7F	JKBZXT40ABA000069 through 026279 ZXT40B – 000002 through 002280	European System Malaysian System

*The above √ symbol indicates this digit number differs from one machine to another.

*The eligible range includes certain number of units inspected by factory and shipped to US and Europe. Detail list is provided to those distributors.

Detail

On some eligible units, the engine mount adjusting collar(s) may be over-tightened at factory, creating excessive stress on weld bead on sides of lower cross pipe of frame. With this condition, if high load is applied in such a way that motorcycle is operated on rough road surfaces or through the potholes, the weld bead on lower cross pipe of frame could crack. Continued use can cause separation of frame, resulting in potential of a crash.

